

图号(Drawing NO.)	SG01 (60KAR) -5Y002-000	型号(Model No.)	GR-37127000-60K	电压(Voltage)	12V DC
图纸	版次:1.0				
Drawing:	<p>常规蓝商标: GR-37127000-60K 12</p>				
客户确认 (Customer APP.):					
参数	减速电机参数 (Geared motor specification):				
Details:	空载电流 (No Load Current) (mA):	≤50			
	空载转速 (No Load Speed) (r. p. m):	117±11			
	额定转矩 (Rated Load Torque) (kgf. cm):	2.5			
	额定电流 (Rated Current) (mA):	≤250			
	额定转速 (Rated Load Speed) (r. p. m):	87±8			
	堵转电流 (Stall Current) (mA):				
	堵转转矩 (Stall Torque) (kgf. cm):				
	旋转方向 (Rotation Direction):	CW/CCW			
备注(Remarks):					
Draw:	Rev:	App.:			

注意事项 (Notes):

- 1, 焊接作业请在短时间内实行。(推荐: 焊接头的温度340~400度, 2秒内实行)
- 2, 在焊接过程中, 请勿使减速机受到冲击或跌落。请勿将减速机输出轴上敲打或压配。Prevent gear motor from being shocked or dropping in mounting process. It is prohibited to strike and crush directly on reducer output shaft.
- 3, 安装螺丝前请先确认外观图所示之形式及长度尺寸。Install the screws after first checking the taps and tap depth against the dimensions entered on the exterior drawing.
- 4, 请小心使用, 勿使黏接剂借由输出轴流入轴内。It is necessary to be careful that the adhesive does not spread along the shaft and flow into the bearing.
- 5, 请不要在安装零件时为了调整位置而从输出轴方向去回转动马达。Do not turn a geared motor by its output shaft when, for example, arranging its position so as to install it.